

CASE NO.	DATE	LOCATION	ISSUE	OUTCOME
2812406/ 2822841/ 4567795/ 2845886	15.7.24/7. 11.24/17.1 2.24/5.6.2 5	Moor Road	Erosion of road edge	Road eroded beneath tarmac at road edge if collapses 600mm drop 1200mm x 400mm 15/8 Investigating 7/11 reported again as eroded further collapsed 300mm into carriageway. 8/11 Asked to look again at 2807897 also & pothole in between 17/12 Inspection done 2/1/25 Looking to do permanent fix once flooding subsided. 20/2/25 Road closed as dealing with pipe in verge to alleviate flooding & then will do repair to drop off 23/4 email received from Jeremy Rowett saying repaired but asking if correct location or other another. 24/4 email sent to Jeremy saying it had not been repaired & barriers still in situ 13/5 Rang Highways to chase for an update from Jeremy 11/6 Update says investigating. 9/7 Contacted highways saying no response still from Jeremy last report gone to another highways officer so they will ask them to liaise with Jeremy to see what can be done. 21/8 Job allocated to be done 4/11 FINALLY WORKS BEING DONE WILL BE COMPLETED 5/11/25. NOW COMPLETE
2846135	8.6.25	Walesby Hill	Potholes	9/7 Rang Anglian Water to see if they had been advised. They had no knowledge of it so have now done a report ref. 27785604 & will investigate within 1 week & report back with update. 9/7 Rang Anglian Water to see if Highways had contacted them, they hadn't so advised them of situation. 10/7 met up with Ben from Anglian Water to show location & explain what Highways said. They will check for any leaks & report back but says the mains in the field not road. AWA confirmed no leaks and therefore I contacted Highways again to advised them & ask for repair to be done 31/8 Job complete contact AWA, however as per report 2846135 on 8/6 regarding a pothole nearby we know the main water supply pipe is not in road as an engineer from AWA confirmed this on 21/7 their ref. 27785604 9/1 Contacting highways again to get them to relook at job. Made complaint as they had not inspected the road simply looked at photos. 23/1 Response received from Highways saying AWA need to confirm not a burst pipe before they inspect it. 23/1 Contacted AWA to ask them to come out to check it which they did 26/1. Road closed 30/1 & major work complete to repair/divert surface water pipe. JOB COMPLETED & ROAD REOPENED.
2867023	26.12.25	Walesby Hill	Road Sunk	

2867600	2.1.26	Bottom of Hall Drive	Blocked drains	Causing flooding down RASEN ROAD which is freezing creating dangerous conditions. 2/1 Investigating 19/2 Inspected by Highways not considered high priority will be done on next scheduled date all drains are cleaned. 8/4 Job allocated
2867984	6.1.26	Top of Walesby Hill	Numerous potholes	9/1 Works planned 24/4 Job completed
2868586/ 2877744	10.1.26/13. 2.26	Catskin Lane	Flooding	10/1 Investigating 19/2 Inspected but no solution found as verges on both side higher than road & no water course to drain water into. NO FURTHER ACTION TO BE TAKEN
4210819	16.1.26	Village Hall	Sign missing	
2872612	27.1.26	Otby Lane	Blocked drain	5/2 No immediate action to be taken
2889445	24.4.26	Catskin Lane (reported by resident)	Verge eroded on both sides	Between Fieldview House and Wolds Away 29/4 Works completed
2890508	5.5.26	Catskin Lane (reported by resident)	Drop off at edge of road	11/5 Assessed no further action to be taken
2890756	7.5.26	Catskin Lane (reported by resident)	Eroded verge	Between Cliff House and Risby Grange. Caused flat tyre 7/5 Being accessed
2890757	7.5.26	Walesby Road (reported by resident)	Potholes	Between Risby Grange and end of road at Tealby 7/5/ Being accessed
2890758	7.5.26	Catskin Lane (reported by resident)	Unsafe tree branch	Snapped & hanging down 7/5 Being assessed
2885493/ 2890942	20.3.26/8.5 .26	Otby Lane (Reported by residents)	Potholes	Large pothole on the edge of manhole cover outside The Rectory. Plus numerous other potholes on Otby Lane case nos. 2885494-2885500&2885502. 11/5 Job allocated. Chased 14/5 Say will be done in 2 weeks with a proper repair not just stone infill
2891134	11.5.26	Catskin Lane (reported by resident)	Road markings	Outside Winfrith, need attention 11/5 Being assessed