

CASE NO.	DATE	LOCATION	ISSUE	OUTCOME
2867600	2.1.26	Bottom of Hall Drive	Blocked drains	Causing flooding down Rasen Road which is freezing creating dangerous conditions. 2/1 Investigating 19/2 Inspected by Highways not considered high priority will be done on next scheduled date all drains are cleaned. 8/4 Job allocated
2868586/2877744	10.1.26/ 13.2.26	Catskin Lane	Flooding	found as verges on both side higher that road & no water course to drain water into. NO FURTHER ACTION TO BE TAKEN
4210819	16.1.26	Village Hall	Sign missing	
2872612	27.1.26	Otby Lane	Blocked drain	5/2 No immediate action to be taken
2889445	24.4.26	Catskin Lane (reported by resident)	Verge eroded on both sides	Between Fieldview House and Wolds Away 29/4 Works completed
2890508	5.5.26	Catskin Lane (reported by resident)	Drop off at edge of road	11/5 Assessed no further action to be taken
2890756	7.5.26	Catskin Lane (reported by resident)	Eroded verge	Between Cliff House and Risby Grange. Caused flat tyre 7/5 Being accessed 9/6 Works complete
2890757	7.5.26	Walesby Road (reported by resident)	Potholes	Between Risby Grange and end of road at Tealby 7/5/ Being accessed 16/6 Works complete

2890758	7.5.26	Catskin Lane (reported by resident)	Unsafe tree branch	Snapped & hanging down 7/5 Being assessed 14/5 Works complete Large pothole on the edge of manhole cover outside The Rectory. Plus numerous other potholes on Otby Lane case nos. 2885494- 2885500&2885502. 11/5 Job allocated. Chased 14/5 Say will be done in 2 weeks with a proper repair not just stone infill 10/6 Works complete
2885493/289 0942	20.3.26/ 8.5.26	Otby Lane (Reported by residents)	Potholes	
2891134	11.5.26	Catskin Lane (reported by resident)	Road markings	Outside Winfrith, need attention 11/5 Being assessed 28/5 Works complete
2891132	11.5.26	Moor Road (reported by resident)	Multiple erosion of road edge	From Red House to railway crossing 4/6 Works complete
2892133	20.5.26	Otby Lane (Reported by residents)	Pothole	Between Highfield Farm and Upper Highfield 26/5 No further action to be taken, considered low priority
29679814 (AWA)	26.6.26	At Junction Otby Lane/Walesby Hill	Water leak in road	Outside Marold water bubbling up from road surface 9/7 Working to resolve issue
2898183	12.7.26	Walesby Hill	Blocked drains	Opposite Greensleeves and adjacent to Blaven. Drains filled with gravel after road resurfacing 13/7 Will be cleaned as part of next scheduled works